

**ATTENTION** 

**BRANCH** 

CERTIFICATE OF CORRECTION



## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Daisuke ITO

Application No.: 10/657,193

Confirmation No.: 1637

Filed: September 9, 2003

U.S. Patent No.: 6,998,339

Issued: February 14, 2006

For: METHOD OF FORMING CONDUCTOR WIRING PATTERN

## REQUEST FOR CERTIFICATE OF CORRECTION

Certificate
MAY 0 9 2006

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

of Correction

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date

May 1, 2006

By:

H I Staak

Registration No. 22,010

1201 New York Ave, N.W., 7th Floor

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501

MAY 09 2006

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,998,339

DATED: February 14, 2006

INVENTOR(S): Daisuke ITO

Column 8, Line 4, delete "at" and insert - - of - - therefor. Column 10, Line 17, after "remaining" insert - - in - -.

MAILING ADDRESS OF SENDER:

STAAS & HALSEY LLP 1201 New York Ave., N.W. 7th Floor Washington, DC 20005 PATENT NO. 6,998,339

No. of add'l copies @ 50¢ per page